

How Ymon checks histograms

- Implementing automatic checking into YMon
- YMon reads in Reference histograms
 - Each bin contains expected value
 - Errors of each bin define tolerance
 - Checking Frequency of N events defined for each monitor
 - Checking happens only for the last N events
 - Histograms will be reset so they contain the last N to 2N events
 - If a bin is out of tolerance, the background pad turns red




What we are up to

- Our plans:
- Short Term (close to completion)
 - Implement a reference plot from the most recent min bias run for the 1d Occupancy plots.
 - Used run 146768
 - Define tolerance as 0.5 * Occupancy in each bin
 - Check frequency is set to the number of events required so that 0.5*Occupancy is 10 sigma away from the expected value

After this

- Communicate changes to detector groups
- Get feedback, and implement:
- Send warnings, errors
- Classifying run as bad/good for detector
- Checking other histograms
- Scaling of histograms with luminosity
- 7 ...





What we need from detector groups

- Good reference files for your detector
 - These will need to be updated as detector status may change
 - Provide us with new YMon output and we will add it to the reference file
- Dead Channel/Hot Channel DB
- Define criteria for checks and giving information to CO
 - Define which histograms need to be checked and how (bin by bin check, KS, ChiSquared)
 - Define tolerance levels for these checks
 - Define statistics required before these checks should be performed
 - What actions should be taken by CO?
 - Page/e-mail expert...
 - Define criteria for classifying run as good or bad
 - Define what should be written to summary file



Current Status for Time of Flight

- Check Frequency :
 - 2300 Events
- Thresholds:
 - CAFE: 100 ADC counts
 - DECAF: 100 ADC counts
- Current "Good Run" Status (for Co's)
 - High Voltage on
 - Less than 5 bad channels total